

# **WOODWARD**

## **SERVICE BULLETIN**

WOODWARD GOVERNOR COMPANY  
One Woodward Way  
P.O. Box 405  
Rockton, Illinois 61072-0405  
USA

C. Material Necessary for Each Aircraft/Engine/Component

See Material - Price and Availability

D. Material Necessary for Each Spare

Not applicable.

E. Reidentified Parts

Not applicable.

F. Tooling - Price and Availability

Not applicable.

### 3. RECOMMENDATIONS

- (1) Recommended Time Between Overhaul (TBO) for Woodward Propeller Governors, Pumps, Auto Feather Valves, and Speed Signal Generators are the same as recommended TBO of engine on which unit is installed except for units listed in the applicable Time Between Overhaul Table.

Reciprocating Engine Governor Time Between Overhaul Table

Governor	TBO
210582	500 Hours
210692	500 Hours
210920	500 Hours
210921	500 Hours

Turboprop Primary Governor Time Between Overhaul Table

Governor	TBO
A210765	2000 Hours
210492	3500 Hours
210508	3500 Hours
210527	3500 Hours
210528	3500 Hours